



YEAR	CLIENT	WORK SCOPE	LOCATION
2020	DOF Subsea	Mooring chain cutting. ROV operated DWS 0814.	Umoroa, New Zealand
2019	Sapura Energy / Vermillion	CALM Buoy mooring chain replacement. DWS 0814.	North West Shelf
2019	BHP	Flexinle flowline, mercury sample coupon cutting. DWS 1230.	Perth
2018	DOF Subsea	Enfield Decom. Riser and chain cutting.	Australia, NW Shelf
2018	Neptune Marine	PNG CALM Buoy decom	Papua New Guinea
2018	ICM	Concrete pile cutting	Australia, Fremantle Harbour
2018	Fugro	DWS contingency tool	New Zealand
2018	DOF Subsea	Pohokura 12" flowline decom	New Zealand
2018	iTech7	DWS 0814 Sole emergency pipeline repair.	Australia, Bass Strait
2017	Baker Hughes	DWS 1230 OMV Casing removal / Slot recovery	New Zealand
2016	Subsea 7	Cutting of flowlines and umbilical	Norway
2015	Aker Subsea	Cutting of 16" riser	Norway
2015	Technip	Contingency for cutting 16" casing	Norway
2015	Subsea 7	Cutting of 9", 10" and 15.5" flexible riser	Norway
2014	Helix Well Ops	Contingency cutting option for multi-string well conductor	UK, North Sea
2014	FugroTSM	Greater Western Flank IRM support	Australia, NW Shelf
2014	Allseas	Wheatstone Trunkline and Julimar Flowline Pipelay Contingency	Australia, NW Shelf
2014	Saipem	Ichthys 42" Pipelay Contingency	Australia, Darwin
2013	PTTEP	ROV operated cutting of 5" mooring chains	Australia, NW Shelf
2013	McDermott	2 nd Phase Contingency for ROV operated cutting of 20" pipeline at 180msw	Australia, NW Shelf
2012	Subsea 7	Cutting of 20" flexible riser	Norway
2012	Technip	Saturation Diver assisted cutting of 18" water induction line at 90msw	UAE
2012	SMIT	Diver assisted cutting of 30" gas induction line at 60msw	UAE
2012	Technip	ROV operated cutting of 6" Production Spool at 520msw	Australia, NW Shelf

More projects and information available upon request.

TRACK RECORD /// DIAMOND WIRE CUTTING